



# LOWER MINNESOTA RIVER WATERSHED DISTRICT

## Executive Summary for Action

Lower Minnesota River Watershed District Board of Managers Meeting  
Wednesday, December 11, 2024

### Agenda Item

#### Item 4. C. – Spring Creek Update

#### Prepared By

Linda Loomis, Administrator

#### Summary

The LMRWD Board of Managers accepted a bid from Sunram Construction for the bank stabilization project at Spring Creek in the City of Carver. Construction began November 18, 2024, and was completed before Thanksgiving. Monday, November 18, 2024, the LMRWD met on site with residents impacted by the project, ISG, project manager and all contractors for the project. All residents were very supportive of the project. The construction went as planned and picture of the project are attached for the Board's information.

Additional planting will occur next Spring and the site will be inspected to see how well vegetation is established (the site was seeded).

The Board will be asked to approve payment for the Construction once the invoice is received. A portion of the cost will be retained until vegetation is successfully established.

#### Attachments

Pictures of project construction

#### Recommended Action

No action recommended – for information.

**Lower Minnesota River Watershed District  
Spring Creek Site 1 and Site 2 Stabilization Construction Photos—November 2024**



*Image 1. Riprap at Site 1*



**Lower Minnesota River Watershed District  
Spring Creek Site 1 and Site 2 Stabilization Construction Photos—November 2024**



*Image 2. Grading and erosion control at Site 2*



**Lower Minnesota River Watershed District  
Spring Creek Site 1 and Site 2 Stabilization Construction Photos—November 2024**



*Image 3. Riprap at Site 2*



**Lower Minnesota River Watershed District  
Spring Creek Site 1 and Site 2 Stabilization Construction Photos—November 2024**



*Image 4. View of Spring Creek from Tracy Carlson's property*



**Lower Minnesota River Watershed District  
Spring Creek Site 1 and Site 2 Stabilization Construction Photos—November 2024**



*Image 5 Riprap protection at Site 2 near the garage*



**Lower Minnesota River Watershed District  
Spring Creek Site 1 and Site 2 Stabilization Construction Photos—November 2024**



*Image 6. Installation of coir logs at Site 1*



**Lower Minnesota River Watershed District  
Spring Creek Site 1 and Site 2 Stabilization Construction Photos—November 2024**



*Image 7. Site 2 Riprap in the foreground and coir logs in the background*



**Lower Minnesota River Watershed District  
Spring Creek Site 1 and Site 2 Stabilization Construction Photos—November 2024**



*Image 8. Grading before placement of coir logs at Site 2*